

EX5600-T0/EX5601-T0/ EX5600-T1/EX5601-T1 Generic

Firmware Release Note

V5.70(ACDZ.0)C0

Date: Sep 8, 2022

Author: Frank Chang

Reviewer:

THIS DOCUMENT CONTAINS PROPRIETARY TECHNICAL INFORMATION THAT IS THE PROPERTY OF THE Zyxel AND SHOULD NOT BE DISCLOSED TO OTHERS IN WHOLE OR IN PART, REPRODUCED, COPIED, OR USED AS BASIS FOR DESIGN, MANUFACTURING OR SALE OF APPARATUS WITHOUT WRITTEN PERMISSION OF Zyxel.

TABLE OF CONTENTS

REVISION HISTORY.....	3
SUPPORTED PLATFORMS:.....	4
VERSIONS:	4
NOTES:.....	4
PUBLIC DOMAIN SOFTWARE ANNOUNCEMENTS	5
KNOWN ISSUES.....	7
MODIFICATIONS IN 5.70(ACDZ.0)C0	7
MODIFICATIONS IN 5.70(ACDZ.0)B7	7
MODIFICATIONS IN 5.70(ACDZ.0)B6	8
MODIFICATIONS IN 5.70(ACDZ.0)B5	8
MODIFICATIONS IN 5.70(ACDZ.0)B4	9
MODIFICATIONS IN 5.70(ACDZ.0)B3	10
MODIFICATIONS IN 5.70(ACDZ.0)B2	10
MODIFICATIONS IN 5.70(ACDZ.0)B1	12

Revision History

Date	Release	Author	Description
2022/04/06	1.0	Frank Chang	FW release for V5.70(ACDZ.0)b1
2022/05/23	2.0	Frank Chang	FW release for V5.70(ACDZ.0)b2
2022/06/22	3.0	Winnie Wen	FW release for V5.70(ACDZ.0)b3
2022/07/18	4.0	Frank Chang	FW release for V5.70(ACDZ.0)b4
2022/08/08	5.0	Frank Chang	FW release for V5.70(ACDZ.0)b5
2022/08/29	6.0	Frank Chang	FW release for V5.70(ACDZ.0)b6
2022/09/05	7.0	Frank Chang	FW release for V5.70(ACDZ.0)b7
2022/09/08	8.0	Frank Chang	FW release for V5.70(ACDZ.0)C0

EX5600-T0/EX5601-T0/EX5600-T1/EX5601-T1
Generic
V5.70(ACDZ.0)C0
Release Note

Date: Sep 08, 2022

Supported Platforms:

Zyxel EX5600-T0/EX5601-T0/EX5600-T1/EX5601-T1 Generic

Versions:

Bootbase version : V2.3 | 08/03/2022 16:53:32

Firmware version : V5.70(ACDZ.0)C0

Kernel version: 5.4.171

WLAN code version: 7.6.2.4

3G WWAN package version: 1.24

VoIP version: HERMAN4 GW 2.4 Release 4.3

Notes:

Public Domain Software Announcements

Open Source Used In Product	Version	From (Source)	License Terms	Modified / Used
attr	2.4.48	http://savannah.nongnu.org/projects/attr	GPLv2	Used
atftp	0.7.4	https://sourceforge.net/projects/atftp/	GPLv2	Modified
bridge-Utils	1.7	https://git.kernel.org/pub/scm/linux/kernel/git/shemminger/bridge-utils.git/	GPLv2	Modified
busybox	1.31.1	https://busybox.net/	GPLv2	Modified
clinkc	2.4	https://sourceforge.net/projects/clinkc/	BSD	Modified
conntrack-tools	1.4.6	https://git.netfilter.org/conntrack-tools/	GPLv2	Used
dnsmasq	2.85	http://www.thekelleys.org.uk/dnsmasq/doc.html	GPLv2/GPLv3	Modified
dropbear	2020.81	https://github.com/mkj/dropbear	MIT	Modified
ebtables	2018-06-27-48cff25d	https://git.netfilter.org/ebtables/	GPLv2	Modified
eventlog	0.2.10	https://github.com/balabit/eventlog	BSD	Used
expat	2.2.10	https://github.com/libexpat/libexpat	MIT	Used
ez-ipupdate	3.0.11b8	http://ez-ipupdate.com/	GPLv2	Modified
gettext	0.19.8.1	http://www.gnu.org/software/gettext/	GPLv3	Used
glib	2.68.4	http://www.gtk.org/	LGPLv2.1	Used
iproute2	5.11.0	https://github.com/shemminger/iproute2	GPLv2	Modified
iptables	1.8.7	https://git.netfilter.org/iptables/	GPLv2	Modified
json-c	0.15	https://github.com/json-c/json-c/downloads	MIT	Modified
libedit	20210419-3.1	http://pkgs.fedoraproject.org/repo/pkgs/libedit/libedit-20080712-2.11.tar.gz/	BSD	Modified
libffi	3.3	http://pkgs.fedoraproject.org/repo/pkgs/libffi/libffi-3.0.11.tar.gz/	MIT	Used
libiconv	1.16	http://www.gnu.org/software/libiconv/	LGPLv2	Modified
libnetfilter_conntrack	1.0.8	https://git.netfilter.org/libnetfilter_conntrack/	GPLv2	Used
libnetfilter_queue	1.0.5	https://git.netfilter.org/libnetfilter_queue/	GPLv2	Used

libnfnetwork	1.0.1	https://git.netfilter.org/libnfnetwork/	GPLv2	Used
libnl-tiny	2020-08-05-c2 91088f	https://github.com/openwrt/openwrt/tree/master/ package/libs/libnl-tiny	GPLv2/LGPLv2.1	Used
libpcap	1.9.1	www.tcpdump.org	BSD	Used
libtool	2.4.6	http://www.gnu.org/software/libtool/	GPLv2	Used
libusb	1.0.24	https://sourceforge.net/projects/libusb/	LGPL 2.1	Used
Linux/Arm Kernel	5.4.171		GPLv2	Modified
logrotate	3.17.0	https://launchpad.net/ubuntu/hardy/i386/logrotate/ e/	GPLv2	Modified
mailsend	1.19	https://github.com/muquit/mailsend/	BSD	Modified
ncurses	6.2	http://ftp.gnu.org/pub/gnu/ncurses/	MIT	Modified
net-snmp	5.8	http://www.net-snmp.org/	ISC/BSD	Modified
ntfs-3g	2021.8.22-3	http://ntfs-3g.org	GPLv2/LGPLv2	Used
ntpclient	2015_365	http://doolittle.icarus.com/ntpclient/	GPLv2	Modified
openssl	1.1.1h	http://www.openssl.org	OpenSSL	Modified
popt	1.16	http://rpm5.org/files/popt/	MIT	Modified
ppp	2.4.3	http://www.roaringpenguin.com/pppoe	GPLv2/BSD	Modified
pure-ftpd	1.0.30	http://pureftpd.org	ISC/BSD	Modified
radvd	1.8	http://www.litech.org/radvd/	BSD	Used
readline	8.1	<a href="http://cnswww.cns.cwru.edu/php/chet/readline/rlt
op.html">http://cnswww.cns.cwru.edu/php/chet/readline/rlt op.html	GPLv2	Used
sqlite	3330000	http://www.sqlite.org/	Public Domain License	Used
syslog-ng	2.0.10	https://github.com/balabit/syslog-ng	GPLv2	Used
tcpdump	4.9.3	http://www.tcpdump.org/	BSD	Used
udhcp	0.9.8	http://udhcp.busybox.net/	GPLv2	Modified
usb-modeswitch	2.1.0	http://www.draisberghof.de/usb_modeswitch/	GPLv2	Used
util-linux	2.36.1	https://github.com/karelzak/util-linux/	GPLv2	Used
wide-dhcpv6	20080615	https://sourceforge.net/projects/wide-dhcpv6/	BSD	Modified
zlib	1.2.11	https://github.com/madler/zlib	zlib	Used

Known issues

Modules	Issue	Risk Impact Information

Modifications in 5.70(ACDZ.0)C0

Based on V5.70(ACDZ.0)b7 to release V5.70(ACDZ.0)C0

● Feature Enhancement

Modified Modules	Features Enhancement List

● Bug Fixed

Modified Modules	Bug Fixed List

Modifications in 5.70(ACDZ.0)b7

● Feature Enhancement

Modified Modules	Features Enhancement List

● Bug Fixed

Modified Modules	Bug Fixed List
WiFi	[#173013] [MPro Mesh][Time:1hr][Occur: 2 time] EX5601 occurs resource temporarily unavailable of the 1905Daemon, it will lead mesh topology disappear during Mesh stress testing period.

--	--

Modifications in 5.70(ACDZ.0)b6

● Feature Enhancement

Modified Modules	Features Enhancement List
WiFi	MTK release new FW bin for DFS certification
WiFi	Country UK support U-NII3 band

● Bug Fixed

Modified Modules	Bug Fixed List
WiFi	Detect radar then wifi reload couldn't select channel

Modifications in 5.70(ACDZ.0)b5

● Feature Enhancement

Modified Modules	Features Enhancement List

● Bug Fixed

Modified Modules	Bug Fixed List
Throughput	[165099] [Throughput] 5G wireless throughput does not pass PQA criterion
System	[170788] [System] Enable Zyxel Exec Env will fail, let ZyEE function cannot work.
Document	[170834] [Document] CPE does not match Default Setting.
NAT	[170779] [NAT] CPE happen call trace when create port trigger and LAN PC run heavy traffic.

SIP	[170773] [RD Internal][VoIP] After CPE establishes a SIP call, the ACS server does GPV ['Device.Services.VoiceService.1.VoiceProfile.1.Line.1.Stats.']. will lead to VoIP cannot work anymore.
TR-143	[167918] [TR-143] Throughput for upload diagnostic does not pass PQA criterion.
MESH	[MPro mesh] AP roaming test found that the record will stay at "IN_STEERING" will not be updated

Modifications in 5.70(ACDZ.0)b4

● Feature Enhancement

Modified Modules	Features Enhancement List

● Bug Fixed

Modified Modules	Bug Fixed List
Stress	[#165089] [Stress] CPE happen call trace (one time) then 24G/5G can not connect to CPE after run 學禮樓 [#167596] [Stress] CPE run Reboot+change pppoe account stress via TR069 will happen coredump. [#169616] [Stress] CPE happen call trace after run NBL stress then stop NBL stress. (stress time > 3 minutes)
Throughput	[#168324] [Throughput] SFP (PMG3000) download throughput only 384M (packet size:1518)
LED	[#168323] [LED] SFP LED display off when CPE connect to OLT2406.
WAN	[#167923] [WAN] When SFP WAN is up, LAN client using "ping" will happen packets lost and playing IPTV will not be smooth
TR-143	[#167918] [TR-143] Throughput for upload diagnostic does not pass PQA criterion.

Modifications in 5.70(ACDZ.0)b3

● Feature Enhancement

Modified Modules	Features Enhancement List

● Bug Fixed

Modified Modules	Bug Fixed List
MGMT	[#165081] [ACTS/MGMT] Restore configuration via ACS, After reboot config not change
IGMP	[#164806] [IGMP] Can't play IPv6 MLD stream
WAN	[#168180] [WAN] CPE not support 2.5G WAN for PMG3000. [#167385] [WAN] In IPoE with VLAN, WLAN client access internet very long time (more than 10 minutes) and ftp upload/download very slow.
LED	[#167912] [LED] CPE internet LED display red when plug in the 3G dongle and get WAN ip. [#167689] [LED] In PPPoE mode, Internet LED display red.
GUI	[#167848] [GUI] Go VoIP > Call History, GUI will keep loading.
Document	[#167610] [Document] CPE's VoIP setting does not match Default Setting. [#165263] [document] PS document not match CPE.
WLAN	[#167373] [WLAN] 24G&5G get IPv4/v6 address, it can not access https web.

Modifications in 5.70(ACDZ.0)b2

● Feature Enhancement

Modified Modules	Features Enhancement List

● Bug Fixed

Modified	Bug Fixed List
----------	----------------

Modules	
WAN	<p>[#165314] [WAN] PMG3000 (V250ABVJ1b1) connect to CPE but it will work fail.</p> <p>[#164920] [WAN] LAN PC can't ping outside after 3G back wan up</p> <p>[#164858] [WAN] VLAN Autohunt function cannot work</p> <p>[#164381] [WAN] In IPoE with VLAN, LAN PC access internet very long time. (more than 15 minutes)</p>
Stress	<p>[#165254] [ACTS/Stress] CPE does not connect to ACS server after run Reboot + change PPP username/password stress via TR069.</p> <p>[#165152] [Stress] CPE happen 45 times call trace after LAN & WLAN overnight Stress testing and doing Firmware Upgrade via TR069</p> <p>[#165080] [Stress] 2.4G and 5G do not send beacon anymore after full loading stress over the weekend and do TR-069 firmware upgrade. (CPE is calibration board)</p> <p>[#165010] [Stress] CPE cannot connect to ACS Server after doing TR0-69 firmware upgrade stress overnight.</p> <p>[#165000] [Stress]CPE happen 3 times call trace when it run USB stress + FW upgrade (from TR069)</p> <p>[#164998] [Stress] CPE WAN cannot get IP after overnight stress</p> <p>[#164888] [Stress] During NBL 72 hrs stress, CPE console keeps printing messages and then reboot.</p>
USB	[#165120] [USB] LAN / WLAN clients download/upload file through samba server will happen call trace.
GUI	[#165045] [GUI] The wireless client icon and informationg will display in Wire page
TR143	[#164817] [ACTS/TR143] Set TR143 Parameters cause the DUT hang
NAT	[#164782] [NAT] Follow DST, CPE should support PCP page.
Document	[#164769] [Document] CPE does not match Default Setting.
IGMP	<p>[#164757] [IGMP] GUI multicast Status will keep loading can't access</p> <p>[#164746] [IGMP] GUI IGMP/MLD page some setting not work</p>
Maintenance	[#164747] [Maintenance] CPE not support SP Domain.
WLAN	<p>[#164710] [WLAN] WLAN Station Status page cannot display any information when wireless client is connected.</p> <p>[#164544] [WLAN] WPS LED isn't amber blinking when WPS process is in progress.</p>

Security	[#164552] [Security] Some MAC Filter CLI can not work. [#164485] [Security] Parental Control work fail.
Routing	[#164480] [Routing] RIP function cannot work. (CPE cannot send RIP packets)
DLNA	[#164422] [DLNA] DLNA work fail.
VoIP	[#168271] [VoIP] CPE has support G.726-24 and G.726-32 codec.

Modifications in 5.70(ACDZ.0)b1

● Feature Enhancement

Modified Modules	Features Enhancement List

● Bug Fixed

Modified Modules	Bug Fixed List
System	[#164359] [System] CPE upgrade FW via expressboot but GUI/Console display V5.70(ACDZ.0)b0